WATER WELL REPORT STATE OF WASHINGTON

Permit No

(1) OWNER: Name HOWARD HARSTAD	Address 18185 NORMANDY TERRACE S.W.	
(2) LOCATION OF WELL: County Island	- NAN, NE 1/2 Sec 34 T30 N. R2	
Bearing and distance from section or subdivision corner 1820 K	ist + 400 South of NW CORNER of See.	31
(3) PROPOSED USE: Domestic Industrial Municipal Irrigation Test Well Other	(10) WELL LOG: Formation: Describe by color, character, size of material and struc	ture, and
	show thickness of aquifers and the kind and nature of the material stratum penetrated, with at least one entry for each change of fi	u in euch
(4) TYPE OF WORK: Owner's number of well (if more than one)	MATERIAL FROM	то
New Well Method: Dug Bored Deepened Cable Driven	Clay Sand Grey 9	
Reconditioned	HARD PAN Gry 6	60
(5) DIMENSIONS: Diameter of well 6 inches.	Sand + Gravel 1/60	160 200
(5) DIMENSIONS: Diameter of well inches. Drilled 290 ft Depth of completed well 288 ft.	Class & Glavel Blue 200	250
	Fine Sand + Clay Who Broy 250	270
(6) CONSTRUCTION DETAILS:	Med. Sand w/w Gray 270	290
Casing installed: 6 "Diam from 0 tt to 218 n.		
Threaded " Diam. from ft. to ft. Welded W " Diam. from ft. to ft.		
Perforations: Yes No Y		
SIZE of perforations in. by in.		
perforations from ft. to ft.		
perforations from ft. to ft. perforations from ft to ft.		····
pertoracions from		
Screens: Yes No - Cook		 - – –
Manufacturer's Name COOK Type Stein/ess Stee Model No 000		
Diam Slot size 10 from It. to It.		
Diam. Slot size from ft. to ft.		
Gravel packed: Yes No Size of gravel:		
Gravel placed fromft. toft.		
Surface seal: Yes X No To what depth? 20 ft.		
Material used in seal BENTONITE		_
Did any strata contain unusable water? Yes 🗌 No 🖪		· ··
Type of water? Depth of strata		¦ · · • · · · · · · · · ·
Manufacturer's Name		
Туре: Н.Р		
(E TER LEVELS: Land-surface elevation above mean sea level		
Stat 1 160'4" ft. below top of well Date 9/21/8/		
Arte: pressure		
Artesian water is controlled by(Cap, valve, etc.)		
(9) WELL TESTS: Drawdown is amount water level is lowered below static level	Work started Sept 2, 19.81. Completed Sept 9	19.8/
Was a nump test made? Yes No If yes, by whom?	WELL DOLL FR'S STATEMENT	
Yield: 38 gai./min. with 13'9"ft. drawdown after 4 hrs	This well was drilled under my jurisdiction and this	report is
0 0	true to the best of my knowledge and bekef.	
December data (time taken as zero when pump turned off) (water level	a colored Marilana Pa	
measured from well top to water level	NAME OF COPPORATION (Type or 1	print)
Time Water Level Time Water Level Time Water Level	Do A - Local	10 00
	Address V.O. BOX SS PREZIMA	
	1 To # Harris	
Date of test hrs	[Signed] ((Well Drifler)	
Bailer test. gal./min. with ft. drawdown after hrs. Artesian flow g.p.m. Date	1 264	/ 10 2 /
Temperature of water Was a chemical analysis made? Yes No	License No. Date Date	g, 10.41